

CERTIFICATE FOR HELATH & SANITATION CONDITION


NO.....301.....

DATE:.....20/09/2024.....

It is certify that **SPRING DALES SCHOOL ALMORA** , Near taxi Stand Link Road Almora 263601 (U.K) has been inspected by me on date :- 18-09-2024 and found that

- 1- School has sufficient ventilation exists in each class rooms.
- 2- The School is providing safe potable drinking water.
- 3- Sufficient number of tags is available including water purifier for drinking water exists.
- 4- Separate toilets and urinals for boy girls, CWSN students and school staff exists.
- 5- The Surrounding area of school is green neat and clean
- 6- School has maintained the hygienic sanitation condition in school premises.

School fulfils the health sanitary conditions and has safe drinking potable water facilities for students and faculty members.


20/09/2024
[Signature with Seal]

Dr Ashok Singh
District Hospital, Almora.